

Date: 8/29/2012

INSTALLATION INSTRUCTIONS Ball Joint Replacement

KIT 93250

This kit replaces parts 57172-88, 43958-88 and 57123-88

Affected Models: Shuttle, Utility, Eagle, Summit, SUV **Tools needed:** Side Cutters, Wrench

Set Parts Needed:

ITEM	CPC P/N	DESCRIPTION	QTY	
1	57190-88	WASHER, LOCK	1	709097
2	43958-00	ROD END, LH THREAD	1	709099
3	57166-88	WASHER STEERING	1	709100
4	57172-00	BALL JOINT, TIE ROD	1	709101
5	57168-00	STEERING BOOT	1	709106
6	10043	CABLE TIE	1	719504
7	7829	NUT, JAM M14 X 1.5	1	749305

NOTE: 57172-92 REPLACES 57172-88 AND 57123-88

